

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>
		<u>Units</u>	<u>Size</u>				
2		1	SR 5/8	98624509	6/1/2016	352821	282 1 20'
							<b>282</b>
3		2	SR 5/8	98624438	6/1/2016	672792	4264 1 20'
							<b>4,264</b>
4		2	SR 3/4	35252480	6/1/2016	833154	7358 1 20'
							<b>7,358</b>
5		1	SRC5/8	98668378	6/1/2016	20021	0 1 20'
							<b>0</b>
6		1	SR 5/8	98624439	6/1/2016	637186	1665 1 20'
							<b>1,665</b>
7		4	SR 3/4	40874420	6/1/2016	1114668	6064 1 20'
							<b>6,064</b>
8		1	SR 3/4	99826386	6/1/2016	1251045	10557 1 20'
							<b>10,557</b>
9		2	SR 3/4	98690451	6/1/2016	123231	0 1 20'
							<b>0</b>
10		1	SR 5/8	98624475	6/1/2016	1014739	1988 1 20'
							<b>1,988</b>
11		1	SR 5/8	98624441	6/1/2016	224406	1982 1 20'
							<b>1,982</b>
12		1	SR 5/8	98624546	6/1/2016	26	0 1 20'
							<b>0</b>
13	Domestic	1	SR 3/4	97953296	6/1/2016	388890	73 1 20'
							<b>73</b>
14		1	SR 3/4	15758924	6/1/2016	107960	1472 1 20'
							<b>1,472</b>
15		1	SR 5/8	98668367	6/1/2016	262052	34 1 20'
							<b>34</b>
16		1	SR 1	9008486	6/1/2016	320356	0 1 20'
							<b>0</b>
17		1	SR 5/8	98624545	6/1/2016	141549	2 1 20'
							<b>2</b>
18		1	SR 5/8	98624442	6/1/2016	148381	6 1 20'
							<b>6</b>
19		2	SR 5/8	94217715	6/1/2016	624962	4871 1 20'

6/6/2016

<u>Customer #</u>		<u>Location</u>	<u>Class</u> <u>Units</u> <u>Size</u>	<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
							<b>4,871</b>	
20	0	Irrigation	1 SR 1	16554176	6/1/2016	1130326	5892	1 20'
							<b>5,892</b>	
20	0	House	1 SR 1	98707017	6/1/2016	463137	10192	1 20'
							<b>10,192</b>	
21	0		1 SR 3/4	97998353	6/1/2016	336800	0	1 20'
							<b>0</b>	
24	0	Stables	1 C 1	98632495	6/1/2016	823551	3450	1 20'
							<b>3,450</b>	
24	0	Residence	1 C 5/8	98668459	6/1/2016	470378	1021	1 20'
							<b>1,021</b>	
79	0		1 SRC5/8	98668408	6/1/2016	384082	4333	1 20'
							<b>4,333</b>	
80	0		1 SRC5/8	98668405	6/1/2016	85388	2117	1 20'
							<b>2,117</b>	
81	0		1 SRC5/8	98668410	6/1/2016	53223	0	1 20'
							<b>0</b>	
82	0		1 SRC5/8	98668407	6/1/2016	260823	906	1 20'
							<b>906</b>	
83	0		1 SRC5/8	98668406	6/1/2016	177466	1809	1 20'
							<b>1,809</b>	
84	0		1 SRC5/8	98668409	6/1/2016	35463	1	1 20'
							<b>1</b>	
86	0		1 SRC5/8	98668473	6/1/2016	72766	472	1 20'
							<b>472</b>	
87	0		1 SRC5/8	98668476	6/1/2016	71048	0	1 20'
							<b>0</b>	
88	0		1 SRC5/8	98668471	6/1/2016	63283	0	1 20'
							<b>0</b>	
89	0		1 SRC5/8	98668474	6/1/2016	98589	398	1 20'
							<b>398</b>	
90	0		1 SRC5/8	98668472	6/1/2016	117789	863	1 20'
							<b>863</b>	
91	0		1 SRC5/8	98668475	6/1/2016	371974	2812	1 20'
							<b>2,812</b>	
92	0		1 SRC5/8	98668375	6/1/2016	176948	150	1 20'
							<b>150</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>				
93	0	1	SRC5/8	98668379	6/1/2016	160333	123 1 20'
							<b>123</b>
94	0	1	SRC5/8	98668376	6/1/2016	89115	0 1 20'
							<b>0</b>
95	0	1	SRC5/8	98668380	6/1/2016	283000	0 1 20'
							<b>0</b>
96	0	1	SRC5/8	98668377	6/1/2016	42582	12 1 20'
							<b>12</b>
97	0	1	SRC5/8	98668401	6/1/2016	94312	445 1 20'
							<b>445</b>
97	2	1	SR 5/8	97951050	6/1/2016	264219	1202 1 20'
							<b>1,202</b>
98	0	1	SRC5/8	98668400	6/1/2016	119727	188 1 20'
							<b>188</b>
99	0	1	SRC5/8	98668404	6/1/2016	241957	345 1 20'
							<b>345</b>
100	0	1	SRC5/8	98668403	6/1/2016	34140	349 1 20'
							<b>349</b>
101	0	1	SRC5/8	98668402	6/1/2016	91001	0 1 20'
							<b>0</b>
102	0	1	SRC5/8	98668399	6/1/2016	607643	1237 1 20'
							<b>1,237</b>
103	0	1	SRC5/8	98668456	6/1/2016	163703	15 1 20'
							<b>15</b>
104	0	1	SRC5/8	98668457	6/1/2016	35676	0 1 20'
							<b>0</b>
105	0	1	SRC5/8	98668454	6/1/2016	43955	727 1 20'
							<b>727</b>
106	1	Irrigation	1 SR 3/4	16622703	6/1/2016	980187	2433 1 20'
							<b>2,433</b>
106	1	Domestic	1 SR 1	98632508	6/1/2016	343939	583 1 20'
							<b>583</b>
107	0		1 SRC5/8	98668455	6/1/2016	126897	1217 1 20'
							<b>1,217</b>
108	0		1 SRC5/8	06003901	6/1/2016	115425	583 1 20'
							<b>583</b>

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>	<u>Units</u>	<u>Size</u>	<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
109 0			1	SRC5/8	15991795	6/1/2016	538536	937	1 20'
								<b>937</b>	
110 0			1	SRC5/8	15991800	6/1/2016	127003	0	1 20'
								<b>0</b>	
111 0			1	SRC5/8	15991796	6/1/2016	146316	1725	1 20'
								<b>1,725</b>	
112 0			1	SRC5/8	15991798	6/1/2016	115940	261	1 20'
								<b>261</b>	
113 0			1	SRC5/8	94566371	6/1/2016	35363	237	1 20'
								<b>237</b>	
114 0			1	SRC5/8	94566372	6/1/2016	7144	0	1 20'
								<b>0</b>	
115 0			1	SRC5/8	94566373	6/1/2016	218712	2235	1 20'
								<b>2,235</b>	
116 0			1	SRC5/8	94566374	6/1/2016	189956	1606	1 20'
								<b>1,606</b>	
117 0			1	SRC5/8	94566375	6/1/2016	61322	171	1 20'
								<b>171</b>	
118 0			1	SRC5/8	94566376	6/1/2016	74074	132	1 20'
								<b>132</b>	
119 0			1	SRC5/8	94566377	6/1/2016	31361	0	1 20'
								<b>0</b>	
120 0			1	SRC5/8	94566378	6/1/2016	63852	0	1 20'
								<b>0</b>	
121 0			1	SRC5/8	94566379	6/1/2016	150051	1841	1 20'
								<b>1,841</b>	
122 0			1	SRC5/8	94566380	6/1/2016	92776	421	1 20'
								<b>421</b>	
123 0			1	SRC5/8	94566381	6/1/2016	153157	26	1 20'
								<b>26</b>	
124 0			1	SRC5/8	15991802	6/1/2016	87354	594	1 20'
								<b>594</b>	
125 0			1	SRC5/8	94566383	6/1/2016	51992	0	1 20'
								<b>0</b>	
126 0			1	SRC5/8	94566384	6/1/2016	27568	496	1 20'
								<b>496</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
127 0		1	SRC5/8	94566385	6/1/2016	59640	8	1 20'
							<b>8</b>	
128 0		1	SRC5/8	94566386	6/1/2016	266917	2297	1 20'
							<b>2,297</b>	
129 0		1	SRC5/8	94566387	6/1/2016	62204	27	1 20'
							<b>27</b>	
130 0		1	SRC5/8	94566388	6/1/2016	95887	449	1 20'
							<b>449</b>	
131 0		1	SRC5/8	94217718	6/1/2016	392045	1005	1 20'
							<b>1,005</b>	
132 0		1	SRC5/8	94217717	6/1/2016	72050	78	1 20'
							<b>78</b>	
179 1		1	SR 5/8	98624403	6/1/2016	1059001	3002	1 20'
							<b>3,002</b>	
181 3		1	SR 5/8	98599620	6/1/2016	703809	8656	1 20'
							<b>8,656</b>	
194 1		2	SR 5/8	98668391	6/1/2016	826652	5193	1 20'
							<b>5,193</b>	
266 1		1	SR 5/8	98599571	6/1/2016	287087	2008	1 20'
							<b>2,008</b>	
316 0		2	SR 5/8	98668420	6/1/2016	1359004	16134	1 20'
							<b>16,134</b>	
316 2		1	SRC5/8	92452042	6/1/2016	839664	21116	1 20'
							<b>21,116</b>	
317 0		1	SR 5/8	98668197	6/1/2016	156107	569	1 20'
							<b>569</b>	
322 0		1	SR 3/4	98690413	6/1/2016	715365	1455	1 20'
							<b>1,455</b>	
323 0		1	SR 3/4	92779849	6/1/2016	3033448	3846	1 20'
							<b>3,846</b>	
324 0	Hot Tub & Spa	1	SR 5/8	98668417	6/1/2016	1122233	5398	1 20'
							<b>5,398</b>	
324 1	By Propane Tank	1	SR 3/4	92452035	6/1/2016	2027677	9210	1 20'
							<b>9,210</b>	
325 0		1	SR 3/4	92452037	6/1/2016	1629456	257	1 20'
							<b>257</b>	
326 1	Domestic	1	SR 1	98632510	6/1/2016	1126264	2129	1 20'

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
						<b>2,129</b>	
326 1	Irrigation	1 SR	3/4	98690434	6/1/2016	965820	30 1 20'
						<b>30</b>	
327 0	Irrigation Meter	1 SR	1	92774884	6/1/2016	1091528	1467 1 20'
						<b>1,467</b>	
327 0	House Meter	1 SR	5/8	98668394	6/1/2016	599199	4181 1 20'
						<b>4,181</b>	
328 0		1 SR	3/4	13257462	6/1/2016	29710	3231 1 20'
						<b>3,231</b>	
331 0		1 SR	3/4	96518920	6/1/2016	920390	8658 1 20'
						<b>8,658</b>	
332 0		1 SR	3/4	15758920	6/1/2016	2024601	193 1 20'
						<b>193</b>	
333 0		1 SR	5/8	98624423	6/1/2016	198965	68 1 20'
						<b>68</b>	
334 0		1 SR	5/8	98690423	6/1/2016	768832	919 1 20'
						<b>919</b>	
335 0		1 SR	3/4	15758921	6/1/2016	1106479	5231 1 20'
						<b>5,231</b>	
336 0		1 SR	5/8	98624422	6/1/2016	395913	4426 1 20'
						<b>4,426</b>	
337 0		1 SR	5/8	98624419	6/1/2016	1226291	5916 1 20'
						<b>5,916</b>	
338 0		1 SR	5/8	98668396	6/1/2016	544504	4633 1 20'
						<b>4,633</b>	
339 0		1 SR	5/8	98668421	6/1/2016	8401	289 1 20'
						<b>289</b>	
340 0		1 SR	5/8	98668419	6/1/2016	863465	0 1 20'
						<b>0</b>	
341 0		2 SR	5/8	98668418	6/1/2016	264123	5 1 20'
						<b>5</b>	
342 0		1 SR	3/4	08419418	6/1/2016	295611	3107 1 20'
						<b>3,107</b>	
343 0		1 SR	5/8	98624420	6/1/2016	193503	2077 1 20'
						<b>2,077</b>	
344 0		1 SR	5/8	98624421	6/1/2016	173838	668 1 20'
						<b>668</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>		
		<u>Units</u>	<u>Size</u>						
345	0	1	SR 5/8	98624510	6/1/2016	307047	3111	1	20'
							<b>3,111</b>		
346	0	1	SR 5/8	94217716	6/1/2016	364923	3392	1	20'
							<b>3,392</b>		
347	0	1	SR 3/4	15758918	6/1/2016	450492	456	1	20'
							<b>456</b>		
348	0	1	SR 5/8	98624512	6/1/2016	968131	10462	1	20'
							<b>10,462</b>		
349	0	1	SR 3/4	16622701	6/1/2016	2457215	28695	1	20'
							<b>28,695</b>		
350	0	1	SR 5/8	98624404	6/1/2016	1060479	9252	1	20'
							<b>9,252</b>		
351	0	2	SR 5/8	98624449	6/1/2016	2074415	8051	1	20'
							<b>8,051</b>		
352	0	1	SR 5/8	98624405	6/1/2016	1118312	2605	1	20'
							<b>2,605</b>		
353	0	1	SR 5/8	98624406	6/1/2016	1558424	12491	1	20'
							<b>12,491</b>		
354	0	1	SR 5/8	98624416	6/1/2016	569691	4816	1	20'
							<b>4,816</b>		
355	0	2	SR 5/8	98624414	6/1/2016	385875	3816	1	20'
							<b>3,816</b>		
356	0	1	SR 5/8	98624431	6/1/2016	545192	724	1	20'
							<b>724</b>		
357	0	1	SR 5/8	98624435	6/1/2016	95192	240	1	20'
							<b>240</b>		
358	0	1	SR 5/8	98624433	6/1/2016	600361	4568	1	20'
							<b>4,568</b>		
359	0	1	SR 5/8	98624463	6/1/2016	422693	0	1	20'
							<b>0</b>		
360	0	1	SR 5/8	98624409	6/1/2016	432471	4820	1	20'
							<b>4,820</b>		
361	0	1	SR 5/8	98624412	6/1/2016	127408	874	1	20'
							<b>874</b>		
362	0	1	SR 5/8	98624452	6/1/2016	203765	0	1	20'
							<b>0</b>		

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>					
363	0	1	SR 5/8	98624460	6/1/2016	123833	967	1 20'
							<b>967</b>	
364	0	1	SR 5/8	98624450	6/1/2016	131156	1324	1 20'
							<b>1,324</b>	
365	0	1	SR 5/8	98624399	6/1/2016	849529	1715	1 20'
							<b>1,715</b>	
366	0	2	SR 3/4	06412451	6/1/2016	1306465	4889	1 20'
							<b>4,889</b>	
367	0	1	SR 5/8	98624459	6/1/2016	218805	2563	1 20'
							<b>2,563</b>	
368	0	2	SR 3/4	06412441	6/1/2016	538873	5146	1 20'
							<b>5,146</b>	
369	0	1	SR 5/8	98668362	6/1/2016	346277	3369	1 20'
							<b>3,369</b>	
370	0	1	SR 5/8	98668388	6/1/2016	159887	240	1 20'
							<b>240</b>	
371	0	1	SR 5/8	97954331	6/1/2016	1377313	0	1 20'
							<b>0</b>	
372	0	1	SR 5/8	98668392	6/1/2016	1230703	8457	1 20'
							<b>8,457</b>	
373	0	1	SR 5/8	98668479	6/1/2016	464095	6466	1 20'
							<b>6,466</b>	
374	0	1	SR 5/8	98668385	6/1/2016	1258123	184	1 20'
							<b>184</b>	
375	0	2	SR 3/4	96581388	6/1/2016	1914386	5020	1 20'
							<b>5,020</b>	
376	0	1	SR 5/8	98668447	6/1/2016	228101	1288	1 20'
							<b>1,288</b>	
377	0	3	SR 3/4	15758914	6/1/2016	603965	10284	1 20'
							<b>10,284</b>	
378	0	1	SR 3/4	15758922	6/1/2016	779535	4454	1 20'
							<b>4,454</b>	
379	0	1	SR 3/4	93381307	6/1/2016	1246212	4362	1 20'
							<b>4,362</b>	
380	0	1	SR 3/4	15758915	6/1/2016	78548	595	1 20'
							<b>595</b>	



6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>
		<u>Units</u>	<u>Size</u>					
381	0	1	SR 5/8	98624432	6/1/2016	129856	59	1 20'
							<b>59</b>	
382	0	1	SR 5/8	98624402	6/1/2016	269652	3825	1 20'
							<b>3,825</b>	
383	0	2	SR 5/8	98624434	6/1/2016	774913	2200	1 20'
							<b>2,200</b>	
384	0	1	SR 5/8	98624436	6/1/2016	883441	7234	1 20'
							<b>7,234</b>	
385	0	1	SR 5/8	98624408	6/1/2016	630599	3220	1 20'
							<b>3,220</b>	
386	0	1	SR 5/8	98624407	6/1/2016	1869282	7373	1 20'
							<b>7,373</b>	
387	0	1	SR 5/8	98622442	6/1/2016	1210161	6529	1 20'
							<b>6,529</b>	
388	0	2	SR 5/8	98624430	6/1/2016	546044	927	1 20'
							<b>927</b>	
389	0	1	SR 5/8	98624565	6/1/2016	194474	451	1 20'
							<b>451</b>	
390	0	1	SR 5/8	98624456b	6/1/2016	232860	2457	1 20'
							<b>2,457</b>	
391	0	1	SR 5/8	98624457	6/1/2016	1094385	0	1 20'
							<b>0</b>	
392	0	1	SR 5/8	97954328	6/1/2016	92024	886	1 20'
							<b>886</b>	
393	0	2	SR 5/8	98624461	6/1/2016	868652	2447	1 20'
							<b>2,447</b>	
393	1	1	SR 5/8	98624446	6/1/2016	454570	5540	1 20'
							<b>5,540</b>	
394	0	1	SR 5/8	98624462	6/1/2016	339813	530	1 20'
							<b>530</b>	
395	0	1	SR 5/8	19421860	6/1/2016	1841477	1511	1 20'
							<b>1,511</b>	
396	0	1	SR 5/8	19421864	6/1/2016	464036	0	1 20'
							<b>0</b>	
397	0	1	SR 5/8	98624400	6/1/2016	346274	189	1 20'
							<b>189</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
398 0		1 SR	3/4	97953294	6/1/2016	559103	7071	1 20'
							<b>7,071</b>	
399 0		1 SR	5/8	98668386	6/1/2016	78031	634	1 20'
							<b>634</b>	
400 0		1 SR	5/8	98668487	6/1/2016	165258	2076	1 20'
							<b>2,076</b>	
401 0		1 SR	5/8	98668478	6/1/2016	1191594	999	1 20'
							<b>999</b>	
402 0		1 SR	5/8	98668498	6/1/2016	162986	2735	1 20'
							<b>2,735</b>	
403 0		1 SR	5/8	98668496	6/1/2016	67906	472	1 20'
							<b>472</b>	
404 0		1 SR	5/8	98624507	6/1/2016	317350	2668	1 20'
							<b>2,668</b>	
405 0		1 SR	5/8	15991791	6/1/2016	771452	14416	1 20'
							<b>14,416</b>	
406 0		1 SR	5/8	98668500	6/1/2016	451139	4129	1 20'
							<b>4,129</b>	
407 0		1 SR	5/8	98624429	6/1/2016	81305	0	1 20'
							<b>0</b>	
408 0		1 SR	5/8	98624410	6/1/2016	622648	1666	1 20'
							<b>1,666</b>	
409 0		1 SR	5/8	98624428	6/1/2016	241169	1628	1 20'
							<b>1,628</b>	
410 0		1 SR	5/8	98624563	6/1/2016	25418	96	1 20'
							<b>96</b>	
411 0		1 SR	5/8	98624568	6/1/2016	232780	161	1 20'
							<b>161</b>	
412 0		1 SR	5/8	98624566	6/1/2016	932376	10634	1 20'
							<b>10,634</b>	
413 0		1 SR	5/8	98624567	6/1/2016	894656	4236	1 20'
							<b>4,236</b>	
414 0		1 SR	5/8	98624464	6/1/2016	234306	3809	1 20'
							<b>3,809</b>	
415 0		1 SR	5/8	98624465	6/1/2016	472743	3297	1 20'
							<b>3,297</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
417 0		1 SR	5/8	98668495	6/1/2016	67922	0	1 20'
							<b>0</b>	
418 0		1 SR	5/8	98668381	6/1/2016	832620	724	1 20'
							<b>724</b>	
419 0		1 SR	5/8	98668372	6/1/2016	51563	835	1 20'
							<b>835</b>	
420 0		1 SR	5/8	98668491	6/1/2016	163994	641	1 20'
							<b>641</b>	
421 0		1 SR	5/8	98668369	6/1/2016	714181	4388	1 20'
							<b>4,388</b>	
422 0		1 SR	5/8	98668490	6/1/2016	386306	3190	1 20'
							<b>3,190</b>	
423 0		1 SR	5/8	98668494	6/1/2016	541092	2403	1 20'
							<b>2,403</b>	
424 0		1 SR	5/8	98668493	6/1/2016	768649	4990	1 20'
							<b>4,990</b>	
425 0	Irrigation left of dr	1 SR	5/8	10057532	6/1/2016	140840	0	1 20'
							<b>0</b>	
425 0		1 SR	5/8	98668467	6/1/2016	312636	359	1 20'
							<b>359</b>	
426 0		1 SR	5/8	98668451	6/1/2016	319245	555	1 20'
							<b>555</b>	
427 0		1 SR	5/8	98668382	6/1/2016	119915	616	1 20'
							<b>616</b>	
428 0		1 SR	5/8	98668373	6/1/2016	94820	0	1 20'
							<b>0</b>	
429 0		1 SR	5/8	98668452	6/1/2016	671458	2279	1 20'
							<b>2,279</b>	
430 0		1 SR	5/8	98668497	6/1/2016	917475	1333	1 20'
							<b>1,333</b>	
431 0		1 SR	5/8	98668482	6/1/2016	327104	0	1 20'
							<b>0</b>	
432 0		1 SR	5/8	98668432	6/1/2016	255624	4677	1 20'
							<b>4,677</b>	
433 0		1 SR	5/8	98668370	6/1/2016	507921	1540	1 20'
							<b>1,540</b>	
434 0		1 SR	5/8	98668468	6/1/2016	1070474	5630	1 20'

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
435	0	1 SR	5/8	98668466	6/1/2016	417589	9 1 20'
							<b>9</b>
436	0	1 SR	5/8	98668470	6/1/2016	720115	454 1 20'
							<b>454</b>
438	1	1 SR	5/8	98624426	6/1/2016	1622431	12676 1 20'
							<b>12,676</b>
439	0	1 SR	5/8	92452039	6/1/2016	1600607	9108 1 20'
							<b>9,108</b>
440	0	1 SR	5/8	98668450	6/1/2016	2461533	3448 1 20'
							<b>3,448</b>
441	0	1 SR	5/8	95926444	6/1/2016	103561	0 1 20'
							<b>0</b>
442	0	1 SR	5/8	95926443	6/1/2016	102785	5725 1 20'
							<b>5,725</b>
443	0	1 SR	5/8	98668448	6/1/2016	88349	0 1 20'
							<b>0</b>
444	0	1 SR	5/8	98624455	6/1/2016	253501	13544 1 20'
							<b>13,544</b>
445	0	1 SR	5/8	98668434	6/1/2016	130502	172 1 20'
							<b>172</b>
446	0	1 SR	5/8	98668431	6/1/2016	51692	435 1 20'
							<b>435</b>
447	0	2 SR	1	94565596	6/1/2016	939982	3491 1 20'
							<b>3,491</b>
447	1	1 SRC	5/8	98624394	6/1/2016	231256	2104 1 20'
							<b>2,104</b>
447	2	0 C	1	98632496	6/1/2016	1409986	10558 1 20'
							<b>10,558</b>
447	3	0 C	5/8	96518771	6/1/2016	470103	3077 1 20'
							<b>3,077</b>
447	3	0 C	5/8	98668483	6/1/2016	105733	1277 1 20'
							<b>1,277</b>
447	4	0 C	1.5	96078644	6/1/2016	655930	0 1 20'
							<b>0</b>
447	4	0 C	1	98632493	6/1/2016	1694874	19052 1 20'
							<b>19,052</b>
447	5	0 C	5/8	95926447	6/1/2016	139803	0 1 20'

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
447 5	New Irrigation	0 C	1.5	98520969	6/1/2016	935990	3730	1 20'
							<b>3,730</b>	
447 5	Post Office	0 C	5/8	98668425	6/1/2016	313504	3308	1 20'
							<b>3,308</b>	
447 6	Entrance Properti	0 C	3/4	34362373	6/1/2016	338976	943	1 20'
							<b>943</b>	
448 0		1 SR	5/8	98624519	6/1/2016	36769	266	1 20'
							<b>266</b>	
449 0		1 SR	5/8	98624518	6/1/2016	326336	5212	1 20'
							<b>5,212</b>	
450 0		1 SR	5/8	98624517	6/1/2016	34923	283	1 20'
							<b>283</b>	
451 0		1 SR	5/8	98624520	6/1/2016	128864	1023	1 20'
							<b>1,023</b>	
452 0		2 SR	5/8	97951057	6/1/2016	1146148	13368	1 20'
							<b>13,368</b>	
452 1		1 SR	5/8	3954329	6/1/2016	652384	5905	1 20'
							<b>5,905</b>	
453 0		1 SR	5/8	97951059	6/1/2016	205148	2841	1 20'
							<b>2,841</b>	
454 0		1 SR	5/8	39680695	6/1/2016	448938	3790	1 20'
							<b>3,790</b>	
455 0		1 SR	5/8	93624443	6/1/2016	878159	2631	1 20'
							<b>2,631</b>	
456 0		1 SR	3/4	17179510	6/1/2016	660189	5100	1 20'
							<b>5,100</b>	
457 0		1 SR	5/8	98624514	6/1/2016	80471	267	1 20'
							<b>267</b>	
458 0		1 SR	5/8	98624513	6/1/2016	1238038	1	1 20'
							<b>1</b>	
459 0		1 SR	3/4	99828454	6/1/2016	1136143	1194	1 20'
							<b>1,194</b>	
460 0		1 SR	5/8	35079022	6/1/2016	1998674	14174	1 20'
							<b>14,174</b>	
461 0		1 SR	5/8	98624552	6/1/2016	479823	3265	1 20'
							<b>3,265</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>
		<u>Units</u>	<u>Size</u>					
462 0		2 SR	5/8	6003899	6/1/2016	339877	913	1 20'
							<b>913</b>	
463 0	Irrigation	1 SEL	5/8	97951052	6/1/2016	1	0	1 20'
							<b>0</b>	
464 0		1 SR	5/8	7954327	6/1/2016	527789	1193	1 20'
							<b>1,193</b>	
465 0		2 SR	5/8	92452041	6/1/2016	587306	4580	1 20'
							<b>4,580</b>	
466 0		2 SR	3/4	98690449	6/1/2016	682093	6392	1 20'
							<b>6,392</b>	
467 0		1 SR	5/8	97951048	6/1/2016	278996	121	1 20'
							<b>121</b>	
468 0		1 SR	5/8	97951051	6/1/2016	1401342	11795	1 20'
							<b>11,795</b>	
469 0		1 SR	5/8	97951053	6/1/2016	668669	43	1 20'
							<b>43</b>	
470 0		1 SR	5/8	97954332	5/26/2016	490869	248	1 20'
					6/1/2016	490953	84	1 20'
							<b>332</b>	
471 0		1 SR	5/8	98599619	6/1/2016	792340	12478	1 20'
							<b>12,478</b>	
472 0		1 SR	5/8	98624564	6/1/2016	404014	547	1 20'
							<b>547</b>	
473 0		1 SR	5/8	98624559	6/1/2016	171977	5516	1 20'
							<b>5,516</b>	
474 0		1 SR	5/8	98599623	6/1/2016	641544	3595	1 20'
							<b>3,595</b>	
475 0		1 SR	5/8	98599621	6/1/2016	792905	2395	1 20'
							<b>2,395</b>	
476 0		1 SR	5/8	95926484	6/1/2016	597447	4198	1 20'
							<b>4,198</b>	
477 0		1 SR	5/8	98599618	6/1/2016	203242	5	1 20'
							<b>5</b>	
478 0		1 SR	5/8	92452036	6/1/2016	205657	7	1 20'
							<b>7</b>	
479 0		1 SR	5/8	98599572	6/1/2016	258998	849	1 20'
							<b>849</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
480		1	SR 5/8	98599622	6/1/2016	666846	2576	1 20'
							<b>2,576</b>	
481		2	SR 5/8	98599575	6/1/2016	878691	11956	1 20'
							<b>11,956</b>	
482		2	SR 5/8	98599574	6/1/2016	482381	3496	1 20'
							<b>3,496</b>	
483	irrigation	1	SR 3/4	9860427	6/1/2016	682989	6	1 20'
							<b>6</b>	
483	Domestic	1	SR 3/4	98690448	6/1/2016	33926	653	1 20'
							<b>653</b>	
484		1	SR 5/8	98599570	6/1/2016	709753	547	1 20'
							<b>547</b>	
485		1	SR 3/4	15758925	6/1/2016	1478327	5904	1 20'
							<b>5,904</b>	
486		2	SR 3/4	11449010	6/1/2016	176529	1014	1 20'
							<b>1,014</b>	
487		1	SR 3/4	17179513	6/1/2016	367080	3722	1 20'
							<b>3,722</b>	
488		2	SR 5/8	98599594	6/1/2016	738554	1680	1 20'
							<b>1,680</b>	
489		1	SR 5/8	98599599	6/1/2016	387997	2468	1 20'
							<b>2,468</b>	
490		1	SR 5/8	98599598	6/1/2016	112011	0	1 20'
							<b>0</b>	
491		1	SR 5/8	98599603	6/1/2016	447166	595	1 20'
							<b>595</b>	
492		1	SR 5/8	98624495	6/1/2016	566274	3857	1 20'
							<b>3,857</b>	
493		2	SR 5/8	98624492	6/1/2016	62416	62	1 20'
							<b>62</b>	
494		1	SR 5/8	98624415	6/1/2016	91968	162	1 20'
							<b>162</b>	
495		1	SR 5/8	98624491	6/1/2016	133952	0	1 20'
							<b>0</b>	
496		2	SR 5/8	98599600	6/1/2016	521386	3871	1 20'
							<b>3,871</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>	<u>Units</u>	<u>Size</u>	<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
497 0			1 SR	5/8	98599604	6/1/2016	105050	0	1 20'
								<b>0</b>	
498 0			1 SR	5/8	98599605	6/1/2016	687224	4853	1 20'
								<b>4,853</b>	
499 0			1 SR	5/8	98599597	6/1/2016	477674	1035	1 20'
								<b>1,035</b>	
500 0			1 SR	5/8	98599601	6/1/2016	406626	15	1 20'
								<b>15</b>	
501 0			1 SR	3/4	11460452	6/1/2016	94293	2313	1 20'
								<b>2,313</b>	
502 0			1 SR	5/8	98624447	6/1/2016	237344	1755	1 20'
								<b>1,755</b>	
503 0			1 SR	5/8	98624445	6/1/2016	368359	2299	1 20'
								<b>2,299</b>	
504 0			1 SRC5/8		98624536	6/1/2016	129499	227	1 20'
								<b>227</b>	
505 0			1 SRC5/8		98624535	6/1/2016	198751	1103	1 20'
								<b>1,103</b>	
506 0			1 SRC5/8		98624527	6/1/2016	166854	1947	1 20'
								<b>1,947</b>	
507 0			1 SRC5/8		98624528	6/1/2016	124051	1448	1 20'
								<b>1,448</b>	
508 0			1 SRC5/8		98624499	6/1/2016	85671	0	1 20'
								<b>0</b>	
509 0			1 SRC5/8		98624530	6/1/2016	68648	0	1 20'
								<b>0</b>	
510 0			1 SRC5/8		98624538	6/1/2016	38734	54	1 20'
								<b>54</b>	
511 0			1 SRC5/8		98624529	6/1/2016	164267	351	1 20'
								<b>351</b>	
512 0			1 SRC5/8		19421862	6/1/2016	138400	14	1 20'
								<b>14</b>	
513 0			1 SRC5/8		98624537	6/1/2016	270484	0	1 20'
								<b>0</b>	
514 0			1 SRC5/8		98624531	6/1/2016	157312	527	1 20'
								<b>527</b>	



6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>					
515 0		1	SRC5/8	98624533	6/1/2016	72779	275	1 20'
							<b>275</b>	
516 0		1	SRC5/8	98624532	6/1/2016	43531	89	1 20'
							<b>89</b>	
518 0		1	SRC5/8	98624501	6/1/2016	363859	1250	1 20'
							<b>1,250</b>	
519 0		1	SRC5/8	98624493	6/1/2016	58315	0	1 20'
							<b>0</b>	
520 0		1	SRC5/8	98624502	6/1/2016	49697	413	1 20'
							<b>413</b>	
521 0		1	SRC5/8	98624579	6/1/2016	121359	356	1 20'
							<b>356</b>	
522 0		1	SRC5/8	98624578	6/1/2016	113394	162	1 20'
							<b>162</b>	
523 0		1	SRC5/8	98624580	6/1/2016	124684	23	1 20'
							<b>23</b>	
524 0		1	SRC5/8	98624577	6/1/2016	142941	1305	1 20'
							<b>1,305</b>	
525 0		1	SRC5/8	98624505	6/1/2016	254768	211	1 20'
							<b>211</b>	
526 0		1	SRC5/8	98624576	6/1/2016	112488	156	1 20'
							<b>156</b>	
527 0		1	SRC5/8	98624575	6/1/2016	43340	0	1 20'
							<b>0</b>	
528 0		1	SRC5/8	98624504	6/1/2016	108450	916	1 20'
							<b>916</b>	
529 0		1	SRC5/8	98624506	6/1/2016	60656	284	1 20'
							<b>284</b>	
531 0		1	SRC5/8	98599611	6/1/2016	180794	91	1 20'
							<b>91</b>	
532 0		1	SRC5/8	98599592	6/1/2016	39991	0	1 20'
							<b>0</b>	
533 0		1	SRC5/8	98599587	6/1/2016	64690	149	1 20'
							<b>149</b>	
534 0		1	SRC5/8	98599609	6/1/2016	195584	1090	1 20'
							<b>1,090</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>					
535	0	1	SRC5/8	98599593	6/1/2016	143283	1196	1 20'
							<b>1,196</b>	
536	0	1	SRC5/8	98599591	6/1/2016	191898	115	1 20'
							<b>115</b>	
537	0	1	SRC5/8	98599588	6/1/2016	153381	0	1 20'
							<b>0</b>	
538	0	1	SRC5/8	98599610	6/1/2016	184323	1670	1 20'
							<b>1,670</b>	
539	0	1	SRC5/8	98599589	6/1/2016	66797	137	1 20'
							<b>137</b>	
540	0	1	SRC5/8	98599606	6/1/2016	60400	1063	1 20'
							<b>1,063</b>	
541	0	1	SRC5/8	98599607	6/1/2016	13817	0	1 20'
							<b>0</b>	
543	0	1	SRC5/8	98599577	6/1/2016	64663	1	1 20'
							<b>1</b>	
544	0	1	SRC5/8	98599584	6/1/2016	148263	504	1 20'
							<b>504</b>	
544	1	1	SRC5/8	98599580	6/1/2016	35223	76	1 20'
							<b>76</b>	
545	0	1	SRC5/8	98599579	6/1/2016	191727	51	1 20'
							<b>51</b>	
546	0	1	SRC5/8	98624593	6/1/2016	152136	1542	1 20'
							<b>1,542</b>	
547	0	1	SRC5/8	98624487	6/1/2016	18431	377	1 20'
							<b>377</b>	
548	0	1	SRC5/8	98624489	6/1/2016	144771	1121	1 20'
							<b>1,121</b>	
549	0	1	SRC5/8	98624522	6/1/2016	106708	0	1 20'
							<b>0</b>	
550	0	1	SRC5/8	98599583	6/1/2016	4744	0	1 20'
							<b>0</b>	
551	0	1	SRC5/8	98599578	6/1/2016	129683	993	1 20'
							<b>993</b>	
552	0	1	SRC5/8	98599585	6/1/2016	22448	176	1 20'
							<b>176</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>					
553 0		1	SRC5/8	98624521	6/1/2016	77037	0	1 20'
							<b>0</b>	
554 0		1	SRC5/8	98624525	6/1/2016	53085	350	1 20'
							<b>350</b>	
555 0		1	SRC5/8	98624486	6/1/2016	17642	0	1 20'
							<b>0</b>	
556 0		1	SRC5/8	98624490	6/1/2016	27173	0	1 20'
							<b>0</b>	
557 0		1	SRC5/8	98599582	6/1/2016	54544	33	1 20'
							<b>33</b>	
558 0		1	SRC5/8	98599576	6/1/2016	54803	570	1 20'
							<b>570</b>	
559 0		1	SRC5/8	98599586	6/1/2016	55328	2	1 20'
							<b>2</b>	
560 0		1	SRC5/8	98624526	6/1/2016	118053	811	1 20'
							<b>811</b>	
561 0		1	SRC5/8	98624488	6/1/2016	101102	0	1 20'
							<b>0</b>	
562 0		1	SRC5/8	98624485	6/1/2016	150363	0	1 20'
							<b>0</b>	
564 0	Laundry	12	HOA5/8	18075106	6/1/2016	473216	1898	1 20'
							<b>1,898</b>	
565 0		1	SRC5/8	98599615	6/1/2016	112386	796	1 20'
							<b>796</b>	
566 0		1	SRC5/8	98668366	6/1/2016	273718	1385	1 20'
							<b>1,385</b>	
567 0		1	SRC5/8	98624597	6/1/2016	210169	1290	1 20'
							<b>1,290</b>	
568 0		1	SRC5/8	98599613	6/1/2016	282809	2797	1 20'
							<b>2,797</b>	
569 0		1	SRC5/8	98624515	6/1/2016	249460	629	1 20'
							<b>629</b>	
570 0		1	SRC5/8	98624496	6/1/2016	506514	5317	1 20'
							<b>5,317</b>	
571 0		1	SRC5/8	98624594	6/1/2016	55474	243	1 20'
							<b>243</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>					
572 0		1	SRC5/8	98624516	6/1/2016	315653	1028	1 20'
							<b>1,028</b>	
573 0		1	SRC5/8	98599616	6/1/2016	24236	0	1 20'
							<b>0</b>	
574 0		1	SRC5/8	98624596	6/1/2016	180736	2128	1 20'
							<b>2,128</b>	
575 0		1	SRC5/8	98599612	6/1/2016	99370	1323	1 20'
							<b>1,323</b>	
576 0		1	SRC5/8	98599617	6/1/2016	36884	1	1 20'
							<b>1</b>	
577 0		13	HOA5/8	98668390	6/1/2016	480859	133	1 20'
							<b>133</b>	
578 1		1	SRC5/8	98668412	6/1/2016	173755	46	1 20'
							<b>46</b>	
579 0		1	SRC5/8	98668415	6/1/2016	62498	174	1 20'
							<b>174</b>	
580 0		1	SRC5/8	98668439	6/1/2016	51901	40	1 20'
							<b>40</b>	
581 0		1	SRC5/8	98668438	6/1/2016	58372	5	1 20'
							<b>5</b>	
582 0		1	SRC5/8	98668416	6/1/2016	10244	0	1 20'
							<b>0</b>	
583 0		1	SRC5/8	98668413	6/1/2016	50242	0	1 20'
							<b>0</b>	
584 0		1	SRC5/8	98668411	6/1/2016	293099	1677	1 20'
							<b>1,677</b>	
585 0		1	SRC5/8	06003896	6/1/2016	45054	0	1 20'
							<b>0</b>	
586 0		1	SRC5/8	98668440	6/1/2016	53770	128	1 20'
							<b>128</b>	
587 0		1	SRC5/8	98668437	6/1/2016	127658	240	1 20'
							<b>240</b>	
588 0		1	SRC5/8	98668435	6/1/2016	71318	22	1 20'
							<b>22</b>	
589 0		1	SRC5/8	98624417	6/1/2016	231284	304	1 20'
							<b>304</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>
		<u>Units</u>	<u>Size</u>					
590 0	laundry	7	HOA5/8	98668449	6/1/2016	736578	14053	1 20'
							<b>14,053</b>	
591 0		1	SRC5/8	98624418	6/1/2016	212453	1049	1 20'
							<b>1,049</b>	
592 0		1	SRC5/8	98624401	6/1/2016	155076	1248	1 20'
							<b>1,248</b>	
593 0		1	SRC5/8	98668433	6/1/2016	130871	0	1 20'
							<b>0</b>	
594 0		1	SRC5/8	98668489	6/1/2016	34378	111	1 20'
							<b>111</b>	
595 0		1	SRC5/8	98624424	6/1/2016	33103	1	1 20'
							<b>1</b>	
596 0		1	SRC5/8	98668426	6/1/2016	42344	0	1 20'
							<b>0</b>	
597 0		1	SRC5/8	98624586	6/1/2016	89606	137	1 20'
							<b>137</b>	
598 0		1	SRC5/8	98624556	6/1/2016	36850	369	1 20'
							<b>369</b>	
599 0		1	SRC5/8	98599569	6/1/2016	28013	0	1 20'
							<b>0</b>	
600 0		1	SRC5/8	98624558	6/1/2016	88113	0	1 20'
							<b>0</b>	
601 0		1	SRC5/8	98624581	6/1/2016	97477	985	1 20'
							<b>985</b>	
602 0		1	SRC5/8	98624582	6/1/2016	74248	0	1 20'
							<b>0</b>	
603 0		1	SRC5/8	98624584	6/1/2016	132535	2406	1 20'
							<b>2,406</b>	
604 0		1	SRC5/8	98624583	6/1/2016	111488	0	1 20'
							<b>0</b>	
605 0		1	SRC5/8	98624560	6/1/2016	118970	3	1 20'
							<b>3</b>	
606 0		1	SRC5/8	98599564	6/1/2016	45687	409	1 20'
							<b>409</b>	
607 0		1	SRC5/8	98599566	6/1/2016	117745	1905	1 20'
							<b>1,905</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
608 0		1	SRC5/8	98599567	6/1/2016	64640	3	1 20'
							<b>3</b>	
609 0		1	SRC5/8	98599568	6/1/2016	110494	373	1 20'
							<b>373</b>	
610 0		1	SRC5/8	98599565	6/1/2016	72669	547	1 20'
							<b>547</b>	
611 0		1	SRC5/8	98624562	6/1/2016	66455	1	1 20'
							<b>1</b>	
612 0		1	SRC5/8	98624557	6/1/2016	30301	64	1 20'
							<b>64</b>	
613 0		1	SRC5/8	98624481	6/1/2016	173525	2214	1 20'
							<b>2,214</b>	
614 0		1	SRC5/8	98624482	6/1/2016	172589	788	1 20'
							<b>788</b>	
615 0		1	SRC5/8	96518767	6/1/2016	24760	109	1 20'
							<b>109</b>	
616 0		1	SRC5/8	98624479	6/1/2016	132324	6	1 20'
							<b>6</b>	
617 0		1	SRC5/8	98624484	6/1/2016	107545	1392	1 20'
							<b>1,392</b>	
618 0		1	SRC5/8	98624480	6/1/2016	104080	136	1 20'
							<b>136</b>	
619 0		1	SRC5/8	98624561	6/1/2016	45790	100	1 20'
							<b>100</b>	
620 0		1	SRC5/8	98624483	6/1/2016	81563	236	1 20'
							<b>236</b>	
621 0	Pool	8	HOA5/8	98624554	6/1/2016	490362	0	1 20'
							<b>0</b>	
622 0		1	SRC5/8	96518769	6/1/2016	263185	57	1 20'
							<b>57</b>	
623 0		1	SRC5/8	98624476	6/1/2016	174381	543	1 20'
							<b>543</b>	
624 0		1	SRC5/8	98624550	6/1/2016	118377	0	1 20'
							<b>0</b>	
625 0		1	SRC5/8	92452040	6/1/2016	80430	33	1 20'
							<b>33</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>	<u>Units</u>	<u>Size</u>	<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
626 0		1 SRC5/8	98624477	6/1/2016	631942	5563	1 20'	<b>5,563</b>	
627 0		1 SRC5/8	98624478	6/1/2016	280816	21	1 20'	<b>21</b>	
628 0		1 SRC5/8	98624474	6/1/2016	146466	1094	1 20'	<b>1,094</b>	
629 0		1 SRC5/8	98624540	6/1/2016	249035	4931	1 20'	<b>4,931</b>	
630 0		1 SRC5/8	98624539	6/1/2016	109981	2158	1 20'	<b>2,158</b>	
631 0		1 SRC5/8	98624571	6/1/2016	226676	45	1 20'	<b>45</b>	
632 0		1 SRC5/8	98624572	6/1/2016	59951	63	1 20'	<b>63</b>	
633 0		1 SRC5/8	96518772	6/1/2016	71830	0	1 20'	<b>0</b>	
634 0		1 SRC5/8	98624587	6/1/2016	344959	3673	1 20'	<b>3,673</b>	
635 0		1 SRC5/8	98624543	6/1/2016	403993	2696	1 20'	<b>2,696</b>	
636 0		1 SRC5/8	98624541	6/1/2016	44135	0	1 20'	<b>0</b>	
637 0		1 SRC5/8	98624544	6/1/2016	41017	685	1 20'	<b>685</b>	
638 0		1 SRC5/8	98624588	6/1/2016	273139	154	1 20'	<b>154</b>	
639 0		1 SRC5/8	98624542	6/1/2016	288097	410	1 20'	<b>410</b>	
640 0		1 SRC5/8	98624591	6/1/2016	66509	362	1 20'	<b>362</b>	
641 0		1 SRC5/8	98624590	6/1/2016	130831	900	1 20'	<b>900</b>	
642 0		1 SRC5/8	98624589	6/1/2016	68082	1598	1 20'	<b>1,598</b>	
643 0		1 SRC5/8	93381288	6/1/2016	94367	374	1 20'	<b>374</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>					
644	0	1	SRC5/8	93381304	6/1/2016	399283	4085	1 20'
							<b>4,085</b>	
645	0	1	SRC5/8	93381287	6/1/2016	93878	117	1 20'
							<b>117</b>	
646	0	1	SRC5/8	93381290	6/1/2016	52920	68	1 20'
							<b>68</b>	
647	0	1	SRC5/8	93381303	6/1/2016	126188	1844	1 20'
							<b>1,844</b>	
648	0	1	SRC5/8	94217714	6/1/2016	125590	2083	1 20'
							<b>2,083</b>	
649	0	1	SRC5/8	94217706	6/1/2016	69661	0	1 20'
							<b>0</b>	
650	0	1	SRC5/8	18075107	6/1/2016	99773	699	1 20'
							<b>699</b>	
651	0	1	SRC5/8	06003898	6/1/2016	238761	2762	1 20'
							<b>2,762</b>	
652	0	1	SRC5/8	94217713	6/1/2016	128632	608	1 20'
							<b>608</b>	
653	0	1	SRC5/8	94217701	6/1/2016	118228	2	1 20'
							<b>2</b>	
654	0	1	SRC5/8	94217705	6/1/2016	276295	3240	1 20'
							<b>3,240</b>	
655	0	1	SRC5/8	18075105	6/1/2016	43282	652	1 20'
							<b>652</b>	
656	0	1	SRC5/8	98599596	6/1/2016	261814	3234	1 20'
							<b>3,234</b>	
657	0	1	SRC5/8	93381293	6/1/2016	169282	626	1 20'
							<b>626</b>	
658	0	1	SRC5/8	18075108	6/1/2016	36403	0	1 20'
							<b>0</b>	
659	0	1	SRC5/8	19421861	6/1/2016	56664	333	1 20'
							<b>333</b>	
660	0	1	SRC5/8	93381281	6/1/2016	165898	158	1 20'
							<b>158</b>	
661	0	1	SRC5/8	93381282	6/1/2016	272874	10162	1 20'
							<b>10,162</b>	



6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>					
662	0	1	SRC5/8	93381283	6/1/2016	455040	576	1 20'
							<b>576</b>	
663	0	1	SRC5/8	93381284	6/1/2016	356654	1395	1 20'
							<b>1,395</b>	
664	0	1	SRC5/8	93381285	6/1/2016	175279	603	1 20'
							<b>603</b>	
665	0	1	SRC5/8	93381300	6/1/2016	554935	2577	1 20'
							<b>2,577</b>	
666	0	1	SRC5/8	93381301	6/1/2016	148225	2986	1 20'
							<b>2,986</b>	
667	0	1	SRC5/8	93381305	6/1/2016	310494	5164	1 20'
							<b>5,164</b>	
668	0	1	SRC5/8	92452043	6/1/2016	56690	0	1 20'
							<b>0</b>	
669	0	1	SRC5/8	92452044	6/1/2016	51092	0	1 20'
							<b>0</b>	
670	0	1	SRC5/8	93381289	6/1/2016	22057	449	1 20'
							<b>449</b>	
671	0	1	SRC5/8	23381296	6/1/2016	218737	67	1 20'
							<b>67</b>	
672	0	1	SRC5/8	23381297	6/1/2016	107911	0	1 20'
							<b>0</b>	
673	0	1	SRC5/8	23381298	6/1/2016	209106	477	1 20'
							<b>477</b>	
674	0	1	SRC5/8	23381299	6/1/2016	203089	162	1 20'
							<b>162</b>	
675	0	1	SR 5/8	98668389	6/1/2016	1306346	10704	1 20'
							<b>10,704</b>	
676	0	1	SRC5/8	98624570	6/1/2016	232244	608	1 20'
							<b>608</b>	
677	0	1	SRC5/8	96578770	6/1/2016	88534	1078	1 20'
							<b>1,078</b>	
678	0	1	SRC5/8	98624574	6/1/2016	230379	1275	1 20'
							<b>1,275</b>	
679	0	1	SRC5/8	98624573	6/1/2016	140620	739	1 20'
							<b>739</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peri</u>
		<u>Units</u>	<u>Size</u>					
680	0	1	SRC5/8	98624470	6/1/2016	233378	4303	1 20'
							<b>4,303</b>	
681	0	1	SRC5/8	98624469	6/1/2016	253893	1033	1 20'
							<b>1,033</b>	
682	0	1	SRC5/8	98624471	6/1/2016	402364	751	1 20'
							<b>751</b>	
683	0	1	SRC5/8	98624472	6/1/2016	282036	0	1 20'
							<b>0</b>	
684	0	1	SRC5/8	98624397	6/1/2016	121566	517	1 20'
							<b>517</b>	
685	0	1	SRC5/8	98624398	6/1/2016	157384	0	1 20'
							<b>0</b>	
686	0	1	SRC5/8	98624396	6/1/2016	189274	200	1 20'
							<b>200</b>	
687	0	1	SRC5/8	98624395	6/1/2016	196360	773	1 20'
							<b>773</b>	
688	0	1	SRC5/8	98624592	6/1/2016	37990	415	1 20'
							<b>415</b>	
689	0	1	SRC5/8	98624569	6/1/2016	187590	765	1 20'
							<b>765</b>	
690	0	1	SRC5/8	98624467	6/1/2016	205135	235	1 20'
							<b>235</b>	
691	0	1	SRC5/8	98624468	6/1/2016	276722	457	1 20'
							<b>457</b>	
692	0	1	SRC5/8	15172726	6/1/2016	1518	238	1 20'
							<b>238</b>	
693	0	1	SRC5/8	98668393	6/1/2016	711	176	1 20'
							<b>176</b>	
694	0	1	SRC5/8	98668398	6/1/2016	41373	0	1 20'
							<b>0</b>	
695	0	1	SRC5/8	98668422	6/1/2016	858269	4205	1 20'
							<b>4,205</b>	
696	0	1	SRC5/8	98668444	6/1/2016	301577	0	1 20'
							<b>0</b>	
697	0	1	SRC5/8	98668442	6/1/2016	100939	9	1 20'
							<b>9</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
698 0		1	SRC5/8	98668441	6/1/2016	43750	431	1 20'
							<b>431</b>	
699 0		1	SRC5/8	98668445	6/1/2016	536830	4976	1 20'
							<b>4,976</b>	
700 0		1	SRC5/8	97954330	6/1/2016	72687	538	1 20'
							<b>538</b>	
701 0		1	SRC5/8	97951055	6/1/2016	185735	1033	1 20'
							<b>1,033</b>	
702 0		1	SRC3/4	08419421	6/1/2016	59468	1167	1 20'
							<b>1,167</b>	
703 0		1	SRC3/4	08419420	6/1/2016	425409	1869	1 20'
							<b>1,869</b>	
704 0		1	SRC5/8	94217709	6/1/2016	99064	0	1 20'
							<b>0</b>	
705 0		1	SRC5/8	94217710	6/1/2016	221388	39	1 20'
							<b>39</b>	
706 0		1	SRC5/8	94217711	6/1/2016	75493	0	1 20'
							<b>0</b>	
707 0		1	SRC5/8	94217712	6/1/2016	355480	4	1 20'
							<b>4</b>	
708 0		1	SR 1	17182325	6/1/2016	1527422	3849	1 20'
							<b>3,849</b>	
709 0		1	SR 3/4	98690412	5/26/2016	2803074	2177	1 20'
					6/1/2016	2803081	7	1 20'
							<b>2,184</b>	
712 1	17 ft edge of pave	1	SEL 3/4	97631713	6/1/2016	2	0	1 20'
							<b>0</b>	
713 0		1	SRC5/8	94566359	6/1/2016	106607	94	1 20'
							<b>94</b>	
714 0		1	SRC5/8	94566361	6/1/2016	47046	496	1 20'
							<b>496</b>	
715 0		1	SRC5/8	94566360	6/1/2016	70098	2	1 20'
							<b>2</b>	
716 0		1	SRC5/8	94566362	6/1/2016	136247	1594	1 20'
							<b>1,594</b>	
717 0		1	SRC5/8	94566364	6/1/2016	58510	837	1 20'
							<b>837</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
718 0		1	SRC5/8	94566365	6/1/2016	61931	0 1 20'
							<b>0</b>
719 0		1	SRC5/8	94566363	6/1/2016	246261	2501 1 20'
							<b>2,501</b>
720 0		1	SRC5/8	94566366	6/1/2016	59306	449 1 20'
							<b>449</b>
721 0		1	SRC5/8	94566367	6/1/2016	20196	0 1 20'
							<b>0</b>
722 0		1	SRC5/8	94566369	6/1/2016	141909	3 1 20'
							<b>3</b>
723 0		1	SRC5/8	94566368	6/1/2016	247086	2051 1 20'
							<b>2,051</b>
724 0		1	SRC5/8	94566370	6/1/2016	95707	427 1 20'
							<b>427</b>
725 0		1	SR 3/4	98690425	6/1/2016	1160772	6185 1 20'
							<b>6,185</b>
726 0		1	SR 3/4	92779847	6/1/2016	1534843	17934 1 20'
							<b>17,934</b>
727 0		1	SR 3/4	93381310	6/1/2016	1410540	12229 1 20'
							<b>12,229</b>
728 0	Irrigation Meter	1	SR 3/4	96581390	6/1/2016	1094502	0 1 20'
							<b>0</b>
728 0	House Meter	1	SR 3/4	97953292	6/1/2016	368972	1922 1 20'
							<b>1,922</b>
729 0		1	SR 3/4	96581389	6/1/2016	1525145	2811 1 20'
							<b>2,811</b>
730 0		1	SR 3/4	97998356	6/1/2016	1338756	4762 1 20'
							<b>4,762</b>
731 0	Irrigation Mtr	1	SR 3/4	97994755	6/1/2016	518332	6074 1 20'
							<b>6,074</b>
731 0	House Mtr	1	SR 1	98632494	6/1/2016	1271077	13807 1 20'
							<b>13,807</b>
733 0	SW Property Corr	1	SR 3/4	92779846	6/1/2016	1663322	9110 1 20'
							<b>9,110</b>
735 0	SE Property Corn	1	SR 3/4	92452038	6/1/2016	1538859	18243 1 20'
							<b>18,243</b>
736 0		1	SR 3/4	92779848	6/1/2016	1086315	8119 1 20'

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
						<b>8,119</b>	
737 0	S/W Property Cor	1 SR	3/4	92452034	6/1/2016	1385719	10 1 20'
						<b>10</b>	
738 0	S/E Property Corr	2 SR	3/4	97994759	6/1/2016	1697437	8263 1 20'
						<b>8,263</b>	
739 0		1 SR	1	98632507	6/1/2016	1409969	6279 1 20'
						<b>6,279</b>	
740 0	N/E Property Corr	1 SR	3/4	97631710	6/1/2016	1387615	7522 1 20'
						<b>7,522</b>	
741 0	15 ft N of Fire Hyc	1 SR	3/4	93381308	6/1/2016	869956	1865 1 20'
						<b>1,865</b>	
742 0	S/E Property Corr	1 SR	3/4	97994760	6/1/2016	1113568	1216 1 20'
						<b>1,216</b>	
743 0	7ft drwy-19ft from	1 SR	3/4	92779844	6/1/2016	1145364	4675 1 20'
						<b>4,675</b>	
744 0		1 SR	3/4	93381306	6/1/2016	1593728	11051 1 20'
						<b>11,051</b>	
745 0	9 ft fm drwy-13 ft	1 SR	3/4	92779845	6/1/2016	895638	5937 1 20'
						<b>5,937</b>	
746 0	12 ft off pave-14 f	1 SR	3/4	92452023	6/1/2016	854635	21553 1 20'
						<b>21,553</b>	
748 0		1 SR	3/4	37994758	6/1/2016	957768	294 1 20'
						<b>294</b>	
749 0	N/E Corner	1 SR	3/4	97631709	6/1/2016	1249875	651 1 20'
						<b>651</b>	
750 0		1 SR	3/4	96518919	6/1/2016	1760289	6913 1 20'
						<b>6,913</b>	
751 0		1 SR	3/4	96518923	6/1/2016	1850257	0 1 20'
						<b>0</b>	
752 0		1 SR	3/4	97994756	6/1/2016	1513006	455 1 20'
						<b>455</b>	
753 0		1 SR	3/4	93381309	6/1/2016	1372125	43521 1 20'
						<b>43,521</b>	
754 0		1 SR	3/4	96518921	6/1/2016	1389733	35 1 20'
						<b>35</b>	
755 0		1 SR	3/4	97631714	6/1/2016	2841762	31133 1 20'

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
						<b>31,133</b>	
756 0		1 SR	3/4	93381311	6/1/2016	2360329	20090 1 20'
							<b>20,090</b>
757 0		1 SR	3/4	98690414	6/1/2016	1278240	5684 1 20'
							<b>5,684</b>
758 0	NE Property Corn	1 SR	3/4	96581387	6/1/2016	2035212	77497 1 20'
							<b>77,497</b>
759 0		1 SR	5/8	95926451	6/1/2016	1470083	2091 1 20'
							<b>2,091</b>
760 0		1 SR	5/8	95926452	6/1/2016	834321	7293 1 20'
							<b>7,293</b>
761 0		1 SR	5/8	95926453	6/1/2016	1654924	2334 1 20'
							<b>2,334</b>
762 0		1 SR	5/8	95926446	6/1/2016	164949	293 1 20'
							<b>293</b>
763 0		1 SR	5/8	95926448	6/1/2016	285941	2544 1 20'
							<b>2,544</b>
764 0		1 SR	5/8	95926449	6/1/2016	1744619	48723 1 20'
							<b>48,723</b>
765 0		1 SR	3/4	96581386	6/1/2016	908816	11828 1 20'
							<b>11,828</b>
765 1	Pool Meter	1 IP	5/8	19421863	6/1/2016	1895807	49188 1 20'
							<b>49,188</b>
766 0	New Station	1 C	3	03116868	6/1/2016	2265200	24100 1 20'
							<b>24,100</b>
766 0	Firehouse	1 C	1.5	15906566	6/1/2016	241580	520 1 20'
							<b>520</b>
766 0	FD-Irr	1 C	1	96518978	6/1/2016	82	0 1 20'
							<b>0</b>
766 0	East Booster	1 C	5/8	98624454	6/1/2016	430924	3483 1 20'
							<b>3,483</b>
767 0	District Office	1 C	2	98749342	6/1/2016	136800	4060 1 20'
							<b>4,060</b>
767 0	Dist Irrigation	1 C	2	98923337	6/1/2016	56440	0 1 20'
							<b>0</b>
768 0	Maintenance Bldg	4 C	3/4	115664181	6/1/2016	142036	1644 1 20'
							<b>1,644</b>
768 0	Hostel	4 C	1.5	18682376	6/1/2016	2015610	8170 1 20'

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>
		<u>Units</u>	<u>Size</u>				
						<b>8,170</b>	
768 0	Clocktower	4 C	1	7444039	6/1/2016	1575678	13256 1 20'
							<b>13,256</b>
768 0	Front Sprinkler	4 C	2	98519265	6/1/2016	450240	6600 1 20'
							<b>6,600</b>
768 0	VIP Mtn House	4 C	1.5	99276714	6/1/2016	1191760	34730 1 20'
							<b>34,730</b>
768 1	Opera House Irrig	0 C	2	98519264	6/1/2016	160	0 1 20'
							<b>0</b>
768 1	Fire Check	0 C	5/8	98624585	6/1/2016	276	0 1 20'
							<b>0</b>
768 1	Opera House	0 C	2	99276503	6/1/2016	3304060	20760 1 20'
							<b>20,760</b>
768 2	Courtside/Emp H:	9 C	1	96518977	6/1/2016	5680341	45401 1 20'
							<b>45,401</b>
768 2	Hub F/Spr	9 C	5/8	98668384	6/1/2016	4722	0 1 20'
							<b>0</b>
768 2	Hub-Domestic	9 C	2	99276500	6/1/2016	1208730	7770 1 20'
							<b>7,770</b>
768 2	Hub-Pool	9 C	2	99276501	6/1/2016	862580	5010 1 20'
							<b>5,010</b>
769 0	Timeshr 1	45 HOA2		00204450	6/1/2016	1024530	2330 1 20'
							<b>2,330</b>
769 0	Watrgdn	45 HOA1		07444038	6/1/2016	7843093	203473 1 20'
							<b>203,473</b>
769 0	Irr #1	45 HOA2		16774297	6/1/2016	5304580	22110 1 20'
							<b>22,110</b>
769 0	Multi-purpose Bld	45 HOA5/8		34211896	6/1/2016	5	1 1 20'
							<b>1</b>
769 1	Timeshare #2	45 HOA2		0020449	6/1/2016	21498610	140400 1 20'
							<b>140,400</b>
769 1	Irrig #2	45 HOA2		17387728	6/1/2016	4194500	13130 1 20'
							<b>13,130</b>
770 0	Fire Service	1 C	5/8	98668383	6/1/2016	152236	0 1 20'
							<b>0</b>
770 0	Plump Jack Hotel	1 C	2	99276506	6/1/2016	24213760	124250 1 20'
							<b>124,250</b>
770 1	Convention Cente	1 C	2	03115931	6/1/2016	2643700	54300 1 20'
							<b>54,300</b>
771 0	Tram	1 C	2	99276795	6/1/2016	6963700	44500 1 20'
							<b>44,500</b>

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
771 1	Oly House	1 C	3	00069177	6/1/2016	25312990	107890	1 20'
							<b>107,890</b>	
771 1	Plaza Sprinklers	1 C	2	52713386	6/1/2016	2337	0	1 20'
							<b>0</b>	
771 1	Olympic House F	1 C	5/8	94217708	6/1/2016	151042	4	1 20'
							<b>4</b>	
771 1	Austrian House	1 C	5/8	98668446	6/1/2016	231670	1096	1 20'
							<b>1,096</b>	
771 2	Parkg- F/S	0 C	5/8	15991799	6/1/2016	490	0	1 20'
							<b>0</b>	
771 2	Locker Room-Hof	0 C	2	98521250	6/1/2016	1462510	6160	1 20'
							<b>6,160</b>	
771 2	Medical Ctr-So W	0 C	5/8	98668443	6/1/2016	1074681	187	1 20'
							<b>187</b>	
771 2	SVSC-parking	0 C	3/4	98690433	6/1/2016	2002	0	1 20'
							<b>0</b>	
771 3	Entrance Irrigatio	0 C	2	18231907	6/1/2016	2615800	18300	1 20'
							<b>18,300</b>	
771 4	Funitel SW	0 C	3/4	98690429	6/1/2016	90384	1187	1 20'
							<b>1,187</b>	
771 4	irrigation	0 C	3/4	99826382	6/1/2016	1096739	24799	1 20'
							<b>24,799</b>	
771 5	Papoose	0 C	5/8	98624473	6/1/2016	718897	448	1 20'
							<b>448</b>	
771 8		0 C	2	99276504	6/1/2016	1226760	2200	1 20'
							<b>2,200</b>	
771 9		0 C	2	99276505	6/1/2016	6288980	31940	1 20'
							<b>31,940</b>	
772 0		59 C	2	04030860-H	6/1/2016	5902	90	1 20'
							<b>90</b>	
772 0	Bldg 1	59 C	2	04030860-L	6/1/2016	1513247	46080	1 20'
							<b>46,080</b>	
772 0	Pool/Hot Tub	59 C	1.5	04128183	6/1/2016	5070710	40250	1 20'
							<b>40,250</b>	
772 0		59 C	3	5008377-H	6/1/2016	282	3	1 20'
							<b>3</b>	
772 0	Health Club-Bldg	59 C	3	5008377-L	6/1/2016	1284479	17779	1 20'
							<b>17,779</b>	
772 1		36 C	2	04030854-H	6/1/2016	2111	62	1 20'
							<b>62</b>	
772 1	Bldg 2	36 C	2	04030854-L	6/1/2016	501212	38204	1 20'
							<b>38,204</b>	



<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
772 2	Bldg 3	59 C	3	1294032	6/1/2016	10366100	44300 1 20'
							<b>44,300</b>
772 2	Bldg 3 Fire Sprink	59 C	5/8	89889451	6/1/2016	672	0 1 20'
							<b>0</b>
772 3	Bldg 4	8 C	1.5	17554475	6/1/2016	654910	2340 1 20'
							<b>2,340</b>
772 4	Bldg 5	8 C	1.5	94195182	6/1/2016	891570	1300 1 20'
							<b>1,300</b>
772 5	Bldg 6 - Fire Sprir	8 C	5/8	98624553	6/1/2016	47495	0 1 20'
							<b>0</b>
772 5	Bldg 6/incl irrig	8 C	1.5	99276715	6/1/2016	2975330	890 1 20'
							<b>890</b>
773 0	Chapel	1 C	5/8	95926445	6/1/2016	2498698	8007 1 20'
							<b>8,007</b>
774 0	Laundry	13 HOA5/8		98624497	6/1/2016	72312	465 1 20'
							<b>465</b>
775 0	Clubhouse	33 C	1	17182323	6/1/2016	226747	1997 1 20'
							<b>1,997</b>
775 0	Hotel - 33 units	33 C	2	98299067	6/1/2016	8760150	66190 1 20'
							<b>66,190</b>
776 0		32 HOA1		98633497	6/1/2016	831766	1182 1 20'
							<b>1,182</b>
777 0	Sprinkler	36 HOA1		98632498	6/1/2016	4071931	671 1 20'
							<b>671</b>
777 0	East End Sprinkle	36 HOA1		98632499	6/1/2016	2702482	0 1 20'
							<b>0</b>
777 0	Sprinkler #2	36 HOA1		98632500	6/1/2016	1414520	164 1 20'
							<b>164</b>
777 0	Sprinkler #3	36 HOA1		98632501	6/1/2016	1178511	646 1 20'
							<b>646</b>
777 0	West End Standp	36 HOA5/8		98668486	6/1/2016	10	0 1 20'
							<b>0</b>
777 0	East End Standpi	36 HOA5/8		98668488	6/1/2016	1	0 1 20'
							<b>0</b>
780 0	Irrigation btwn #3	21 HOA1.5		19690045	6/1/2016	2223700	1500 1 20'
							<b>1,500</b>
780 0	Hose Bib #3-Com	21 HOA5/8		98668460	6/1/2016	776183	465 1 20'
							<b>465</b>
780 0	Hose Bib- #1	21 HOA5/8		98668463	6/1/2016	1	0 1 20'
							<b>0</b>

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
780 0	Sprinkler #2 East	21	HOA5/8	98668485	6/1/2016	579170	0 1 20'
							<b>0</b>
781 0	#5 East Side of L:	0	HOA5/8	19532148	6/1/2016	9783	1 1 20'
							<b>1</b>
781 0	#6-Upper Loop-Lc	0	HOA5/8	97951056	6/1/2016	134614	30 1 20'
							<b>30</b>
781 0	#2 Lower = Lot 4	0	HOA5/8	97951058	6/1/2016	1070504	0 1 20'
							<b>0</b>
781 0	#4 - Lakeside Lot	0	HOA5/8	98668423	6/1/2016	1	0 1 20'
							<b>0</b>
781 0	#3 - Lower Media	0	HOA5/8	98668461	6/1/2016	1322428	2639 1 20'
							<b>2,639</b>
781 0	#7-Upper Tennis	0	HOA5/8	98668464	6/1/2016	1414760	207 1 20'
							<b>207</b>
782 0	Plaza Bldg-btwn c	0	C 3	05011398	6/1/2016	60677700	594700 1 20'
							<b>594,700</b>
782 0	Plaza Hardscape-	0	C 2	18231904	6/1/2016	6120000	6100 1 20'
							<b>6,100</b>
782 0	Hotel Entrance La	0	C 2	18231906	6/1/2016	7511500	2200 1 20'
							<b>2,200</b>
782 0	Maint Build	0	C 1.5	98749345	6/1/2016	765380	10790 1 20'
							<b>10,790</b>
782 0	Maint Irrigation Be	0	C 1.5	99276713	6/1/2016	20	0 1 20'
							<b>0</b>
783 0	Irrigation	16	HOA2	99276796	6/1/2016	1073990	660 1 20'
							<b>660</b>
785 0	Fire Sprinklers	0	C 5/8	97951049	6/1/2016	20	0 1 20'
							<b>0</b>
785 0	Irrigation	0	C 2	98522267	6/1/2016	2042600	0 1 20'
							<b>0</b>
785 0	Bldgs A,B,C	0	C 2	99276502	6/1/2016	14774420	107520 1 20'
							<b>107,520</b>
785 1	New Dorm	1	C 2	08166081	6/1/2016	3821450	89410 1 20'
							<b>89,410</b>
785 1	Maintenance Bldg	1	C 5/8	98668484	6/1/2016	1	1 1 20'
							<b>1</b>
786 0		35	HOA2	98521249	6/1/2016	1230740	0 1 20'
							<b>0</b>
786 0	Sprinkler #2	35	HOA1.5	98748540	6/1/2016	883510	0 1 20'
							<b>0</b>
786 1	Swimpool/Bath Hi	0	C 1.5	17387698	6/1/2016	176220	863 1 20'

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>
		<u>Units</u>	<u>Size</u>				
787 0	89-FF 6in	0 C	6	1397127	6/1/2016	4400	0 1 20'
							<b>0</b>
787 0	Hwy 89-2 in	0 C	2	99276499	6/1/2016	27475290	230990 1 20'
							<b>230,990</b>
788 0	7-11 Store	0 C	1.5	19536738	6/1/2016	544407	5742 1 20'
							<b>5,742</b>
794 0	Tav Inn II-F/S	21 HOA5/8		18075103	6/1/2016	7	0 1 20'
							<b>0</b>
794 0	Tav II-HOA-Irrigat	21 HOA3/4		98690416	6/1/2016	753975	0 1 20'
							<b>0</b>
795 0	Bldg B-North Side	8 HOA1		98632504	6/1/2016	630874	782 1 20'
							<b>782</b>
795 0	Bldg A No West t	8 HOA1		98632505	6/1/2016	775117	3276 1 20'
							<b>3,276</b>
809 0	House Meter	1 SR	1	98632502	6/1/2016	306925	603 1 20'
							<b>603</b>
809 0	Irrigation	1 SR	1	98632503	6/1/2016	1056804	2613 1 20'
							<b>2,613</b>
822 0		1 SR	3/4	97998357	6/1/2016	816883	3557 1 20'
							<b>3,557</b>
827 0		1 SR	3/4	97998355	6/1/2016	1670633	24238 1 20'
							<b>24,238</b>
828 0		1 SR	3/4	98690447	6/1/2016	2209393	17447 1 20'
							<b>17,447</b>
847 0		1 SR	3/4	98690445	6/1/2016	1154841	8 1 20'
							<b>8</b>
848 0		1 SR	3/4	98690446	6/1/2016	1009263	0 1 20'
							<b>0</b>
850 0		1 SR	3/4	98690418	6/1/2016	412252	1051 1 20'
							<b>1,051</b>
851 0		1 SR	3/4	98690426	6/1/2016	840940	4351 1 20'
							<b>4,351</b>
852 0		1 SR	3/4	98690422	6/1/2016	2145023	8751 1 20'
							<b>8,751</b>
853 0		1 SR	3/4	98690424	6/1/2016	707123	1473 1 20'
							<b>1,473</b>

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>
		<u>Units</u>	<u>Size</u>					
855 0		1 SR	1	16554175	6/1/2016	1428850	44858	1 20'
							<b>44,858</b>	
856 0		1 SR	3/4	99826384	6/1/2016	1066856	24125	1 20'
							<b>24,125</b>	
860 0		1 I	5/8	9862449	6/1/2016	1508907	2901	1 20'
							<b>2,901</b>	
861 0		1 SR	1	18081559	6/1/2016	714113	44	1 20'
							<b>44</b>	
862 0		1 SR	3/4	99826385	6/1/2016	2608316	22728	1 20'
							<b>22,728</b>	
863 0		1 SR	1	98707016	6/1/2016	1506300	23	1 20'
							<b>23</b>	
865 0	Domestic	1 SR	3/4	17179508	6/1/2016	663437	5933	1 20'
							<b>5,933</b>	
866 0		1 SR	3/4	99826383	6/1/2016	1209113	731	1 20'
							<b>731</b>	
868 0		1 SR	3/4	99826387	6/1/2016	392599	1	1 20'
							<b>1</b>	
869 0		1 SR	5/8	98668395	6/1/2016	780906	1911	1 20'
							<b>1,911</b>	
871 0		1 SR	1	98632511	6/1/2016	2084852	359	1 20'
							<b>359</b>	
872 0		1 SR	3/4	97953295	6/1/2016	829005	0	1 20'
							<b>0</b>	
873 0		1 SR	3/4	99826453	6/1/2016	323661	0	1 20'
							<b>0</b>	
874 0		1 SR	3/4	98690442	6/1/2016	1173579	7540	1 20'
							<b>7,540</b>	
875 0		1 SR	3/4	08419419	6/1/2016	297965	4338	1 20'
							<b>4,338</b>	
876 0		1 SR	3/4	98690444	6/1/2016	341193	5595	1 20'
							<b>5,595</b>	
877 0		1 SRC	5/8	94217704	6/1/2016	329189	236	1 20'
							<b>236</b>	
878 0		1 SRC	5/8	98599590	6/1/2016	135187	1241	1 20'
							<b>1,241</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
879 0		1 SR	1	92452045	6/1/2016	2485306	11021	1 20'
							<b>11,021</b>	
880 0		1 SR	1	98791620	6/1/2016	1146914	8969	1 20'
							<b>8,969</b>	
881 0		1 SR	1	98707015	6/1/2016	1265707	3397	1 20'
							<b>3,397</b>	
883 0		1 SR	3/4	97631711	6/1/2016	796968	4	1 20'
							<b>4</b>	
884 0		1 SR	3/4	17179512	6/1/2016	747818	4341	1 20'
							<b>4,341</b>	
885 0		1 SR	1	98632509	6/1/2016	141257	597	1 20'
							<b>597</b>	
886 0		1 SR	5/8	98624453	6/1/2016	1423415	7564	1 20'
							<b>7,564</b>	
887 0		1 SR	3/4	15758916	6/1/2016	1212175	366	1 20'
							<b>366</b>	
888 1		1 SR	1	16554173	6/1/2016	2531217	79564	1 20'
							<b>79,564</b>	
895 0	Domestic	1 SR	1	16554171	6/1/2016	195333	420	1 20'
							<b>420</b>	
895 0	Irrigation	1 SR	3/4	98690435	6/1/2016	618253	6583	1 20'
							<b>6,583</b>	
896 0	Unit 42	1 SRC	5/8	19927091	6/1/2016	104824	0	1 20'
							<b>0</b>	
897 0	Unit #38	1 SRC	5/8	19927096	6/1/2016	35261	137	1 20'
							<b>137</b>	
898 0	Unit #37	1 SRC	5/8	19927098	6/1/2016	252468	1636	1 20'
							<b>1,636</b>	
899 0	Unit 36	1 SRC	5/8	19927100	6/1/2016	217924	424	1 20'
							<b>424</b>	
900 0	Unit 40	1 SRC	5/8	19927092	6/1/2016	99692	544	1 20'
							<b>544</b>	
901 0	Unit #41	1 SRC	5/8	19927088	6/1/2016	77450	88	1 20'
							<b>88</b>	
902 0	Unit #39	1 SRC	5/8	19927095	6/1/2016	103099	0	1 20'
							<b>0</b>	
903 0	Unit #43	1 SRC	5/8	19927087	6/1/2016	133389	0	1 20'
							<b>0</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
904	0	#44	1 SRC5/8	19927084	6/1/2016	116536	9 1 20'
							<b>9</b>
905	0	Unit #45	1 SRC5/8	19927083	6/1/2016	361717	3647 1 20'
							<b>3,647</b>
906	0	Unit #46	1 SRC5/8	19927082	6/1/2016	103716	0 1 20'
							<b>0</b>
907	0	Unit #47	1 SRC5/8	19927099	6/1/2016	101347	115 1 20'
							<b>115</b>
908	0	Unit #48	1 SRC5/8	19927097	6/1/2016	34080	6 1 20'
							<b>6</b>
909	0	Unit #49	1 SRC5/8	19927093	6/1/2016	103119	1 1 20'
							<b>1</b>
910	0	Unit #50	1 SRC5/8	19927094	6/1/2016	205641	8488 1 20'
							<b>8,488</b>
911	0	Unit #51	1 SRC5/8	19927090	6/1/2016	170967	2343 1 20'
							<b>2,343</b>
912	0	Unit #52	1 SRC5/8	19927089	6/1/2016	51624	208 1 20'
							<b>208</b>
913	0	Unit #53	1 SRC5/8	19927085	6/1/2016	237323	8444 1 20'
							<b>8,444</b>
914	0	Unit #54	1 SRC5/8	19927086	6/1/2016	209466	59 1 20'
							<b>59</b>
915	0	Unit #55	1 SRC5/8	19927081	6/1/2016	119068	91 1 20'
							<b>91</b>
916	0	Unit #56	1 SRC5/8	19927080	6/1/2016	200621	756 1 20'
							<b>756</b>
919	0		1 SR 5/8	98624511	6/1/2016	742336	7151 1 20'
							<b>7,151</b>
920	0		1 SR 3/4	37994757	6/1/2016	1067878	7525 1 20'
							<b>7,525</b>
921	0		1 SR 1	07233574	6/1/2016	251063	433 1 20'
							<b>433</b>
922	0		1 SR 3/4	98690415	6/1/2016	1273893	17635 1 20'
							<b>17,635</b>
927	0		1 SR 3/4	98690436	5/19/2016	1447863	984 1 20'

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
927 0		1 SR	3/4	98690436	6/1/2016	1449054	1191	1 20'
							<b>2,175</b>	
928 0		1 SR	3/4	98690417	6/1/2016	238674	86	1 20'
							<b>86</b>	
929 0		1 SR	3/4	98690438	6/1/2016	1046353	3141	1 20'
							<b>3,141</b>	
930 0		1 SRC	5/8	98668387	6/1/2016	103840	109	1 20'
							<b>109</b>	
931 1	Bldg D	1 C	6	02000997	6/1/2016	50969200	303300	1 20'
							<b>303,300</b>	
931 1	Bldg D-F/S	1 C	5/8	18075104	6/1/2016	173	11	1 20'
							<b>11</b>	
931 1	Bldg D-Irr	1 C	2	18231940	6/1/2016	2466707	16842	1 20'
							<b>16,842</b>	
932 0		1 SR	3/4	16622710	6/1/2016	1585048	119	1 20'
							<b>119</b>	
935 0		1 SRC	5/8	98599581	6/1/2016	80785	486	1 20'
							<b>486</b>	
936 0		1 SR	5/8	98599602	6/1/2016	366666	5384	1 20'
							<b>5,384</b>	
937 0		1 SRC	5/8	98668465	6/1/2016	107637	2	1 20'
							<b>2</b>	
938 0		1 SR	3/4	15758919	6/1/2016	1171158	7048	1 20'
							<b>7,048</b>	
939 0	1st Ascent	0 C	6	01025216	6/1/2016	54064000	294800	1 20'
							<b>294,800</b>	
939 0	1st Ascent-F/S	0 C	5/8	15991792	6/1/2016	48	5	1 20'
							<b>5</b>	
939 0	1st Irrig	0 C	2	17389833	6/1/2016	4839400	135100	1 20'
							<b>135,100</b>	
1023 0	Irrigation	40 C	2	14294284	6/1/2016	174147	19088	1 20'
							<b>19,088</b>	
1023 0	Bldg 7	40 C	3	15910141	6/1/2016	6068460	20310	1 20'
							<b>20,310</b>	
1023 0	Laundry room, so	40 C	5/8	98668365	6/1/2016	232	0	1 20'
							<b>0</b>	
1026 0		1 SR	3/4	17179511	6/1/2016	904097	2233	1 20'
							<b>2,233</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
1027 0	Domestic	1 SR	1	16554172	6/1/2016	1642836	438	1 20'
							<b>438</b>	
1030 0		1 SR	3/4	98690430	6/1/2016	1154879	1945	1 20'
							<b>1,945</b>	
1045 0	Irrigation	1 SR	3/4	06141978	6/1/2016	165107	1966	1 20'
							<b>1,966</b>	
1045 0	domestic	1 SR	3/4	18664728	6/1/2016	133906	0	1 20'
							<b>0</b>	
1048 0		1 SR	3/4	99826388	6/1/2016	1151156	7429	1 20'
							<b>7,429</b>	
1049 0	SV Park	1 C	2	18231939	6/1/2016	709560	350	1 20'
							<b>350</b>	
1050 0		1 SR	3/4	98690431	6/1/2016	840007	1729	1 20'
							<b>1,729</b>	
1051 0		2 SR	3/4	96581385	6/1/2016	2266573	20337	1 20'
							<b>20,337</b>	
1056 0		1 SR	5/8	98668469	6/1/2016	1164749	0	1 20'
							<b>0</b>	
1057 0		1 SR	3/4	98690428	6/1/2016	1215295	1925	1 20'
							<b>1,925</b>	
1058 0		1 SR	1	17182326	6/1/2016	930091	12	1 20'
							<b>12</b>	
1060 0		1 SR	1	18081563	6/1/2016	1658482	2664	1 20'
							<b>2,664</b>	
1061 0		1 SR	3/4	18664726	6/1/2016	1428383	4637	1 20'
							<b>4,637</b>	
1077 0	Irrigation	1 SR	3/4	16622709	6/1/2016	1402435	16794	1 20'
							<b>16,794</b>	
1077 0	Domestic	1 SR	1	18084562	6/1/2016	548279	1304	1 20'
							<b>1,304</b>	
1078 0		1 SR	3/4	16622706	6/1/2016	1782841	254	1 20'
							<b>254</b>	
1081 0		1 SR	3/4	19532144	6/1/2016	731625	1308	1 20'
							<b>1,308</b>	
1082 0		1 SR	3/4	06412450	6/1/2016	1428815	1	1 20'
							<b>1</b>	
1087 0		1 SRC	5/8	98668436	6/1/2016	47692	87	1 20'



6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>					
1091 0		1	SR 3/4	15758917	6/1/2016	1663918	7408	1 20'
							<b>7,408</b>	
1107 0		2	SR 5/8	98624440	6/1/2016	263842	699	1 20'
							<b>699</b>	
1108 0		1	SRC5/8	93381302	6/1/2016	196085	3590	1 20'
							<b>3,590</b>	
1109 0		1	SR 3/4	98690439	6/1/2016	1100108	7384	1 20'
							<b>7,384</b>	
1110 0		1	SRC5/8	98624500	6/1/2016	186754	1205	1 20'
							<b>1,205</b>	
1115 0		238	HOA3	13257900H	6/1/2016	4591627	401718	1 20'
							<b>401,718</b>	
1115 0		238	HOA4	13257900L	6/1/2016	76974	1419	1 20'
							<b>1,419</b>	
1120 0		1	SR 1	17182324	6/1/2016	1333941	251	1 20'
							<b>251</b>	
1121 0		1	SR 3/4	16622705	6/1/2016	663742	5071	1 20'
							<b>5,071</b>	
1122 0		1	SR 1	17182327	6/1/2016	765215	1610	1 20'
							<b>1,610</b>	
1123 0		1	SR 3/4	16622708	6/1/2016	1869005	23429	1 20'
							<b>23,429</b>	
1124 0		1	SR 3/4	16622704	6/1/2016	1451715	7118	1 20'
							<b>7,118</b>	
1125 0		1	SR 3/4	17179509	6/1/2016	639567	5913	1 20'
							<b>5,913</b>	
1126 0		1	SRC5/8	98668453	6/1/2016	134769	370	1 20'
							<b>370</b>	
1139 0		1	SR 1	18081561	6/1/2016	1520174	170	1 20'
							<b>170</b>	
1142 0		1	SR 3/4	98690437B	6/1/2016	567987	874	1 20'
							<b>874</b>	
1145 0		1	SR 3/4	16622702	6/1/2016	861243	10157	1 20'
							<b>10,157</b>	
1147 0		1	SR 1	19536737	6/1/2016	618065	292	1 20'
							<b>292</b>	

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>	
		<u>Units</u>	<u>Size</u>					
1147 0	Irrigation	1 SR	3/4	98624503	6/1/2016	777539	14873	1 20'
							<b>14,873</b>	
1150 0		1 SR	5/8	06003897	6/1/2016	679300	3746	1 20'
							<b>3,746</b>	
1152 0		1 SR	3/4	06412440	6/1/2016	233715	518	1 20'
							<b>518</b>	
1155 0		1 SR	3/4	19532147	6/1/2016	935423	7382	1 20'
							<b>7,382</b>	
1157 0		1 SR	3/4	98690432	6/1/2016	1451044	454	1 20'
							<b>454</b>	
1160 0		1 SR	1	98632490	6/1/2016	932384	9207	1 20'
							<b>9,207</b>	
1161 0		1 SEL	1	07233575	6/1/2016	1499	0	1 20'
							<b>0</b>	
1163 0		1 SR	1	07233577	6/1/2016	854510	6595	1 20'
							<b>6,595</b>	
1206 0	domestic	1 SEL	3/4	967631712	6/1/2016	30	0	1 20'
							<b>0</b>	
1207 0		1 SR	5/8	98668371	6/1/2016	630464	2303	1 20'
							<b>2,303</b>	
1224 0	Irrigation	1 SR	1	09008488	6/1/2016	268661	8072	1 20'
							<b>8,072</b>	
1224 0	Domestic	1 SR	1	09008489	6/1/2016	87862	734	1 20'
							<b>734</b>	
1227 0		1 SR	3/4	19532146	6/1/2016	923643	212	1 20'
							<b>212</b>	
1234 0		1 SRC	5/8	98624523	6/1/2016	74188	149	1 20'
							<b>149</b>	
1238 0		1 SR	1	16554178a	6/1/2016	509983	535	1 20'
							<b>535</b>	
1244 0		1 SRC	5/8	15991801	6/1/2016	177435	78	1 20'
							<b>78</b>	
1251 0	Buchman Irrig	1 SR	3/4	97953291	6/1/2016	497155	0	1 20'
							<b>0</b>	
1251 0	Buchman Res	1 SR	5/8	986244	6/1/2016	251745	296	1 20'
							<b>296</b>	
1252 0	Irrigation Meter	1 SR	3/4	16622707	6/1/2016	283309	0	1 20'

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>		<u>Serial No</u>	<u>Reading</u>	<u>Consumptn</u>	<u>Perio</u>
		<u>Units</u>	<u>Size</u>				
1252 0	Cushing House-D	1 SR	3/4	98690441	6/1/2016	471931	464 1 20'
							<b>464</b>
1256 0	Domestic	1 SR	3/4	06141978	6/1/2016	127458	2966 1 20'
							<b>2,966</b>
1256 0	Irrigation	1 SR	5/8	09590507	6/1/2016	400045	28573 1 20'
							<b>28,573</b>
1260 0	Domestic	0 SR	3/4	92779845	6/1/2016	91647	661 1 20'
							<b>661</b>
1260 0	Irrigation	0 SR	3/4	98624549	6/1/2016	938681	29623 1 20'
							<b>29,623</b>
1267 0	Temp HOA	0 HOA	1.5	12197187	6/1/2016	3695364	112606 1 20'
							<b>112,606</b>
1273 0	Irrigation: front of	1 SEL	3/4	13077076	6/1/2016	649	546 1 20'
							<b>546</b>
1273 0	Domestic	1 SEL	3/4	18077074	6/1/2016	5463	1 1 20'
							<b>1</b>
1274 0	Irrigation	1 SEL	3/4	13042519	6/1/2016	1	0 1 20'
							<b>0</b>
1274 0	Residential	1 SEL	3/4	13257461	6/1/2016	19580	478 1 20'
							<b>478</b>
1275 0	Irrigation	1 SEL	3/4	13042520	6/1/2016	0	0 1 20'
							<b>0</b>
1275 0	Domestic	1 SEL	3/4	13257463	6/1/2016	23820	304 1 20'
							<b>304</b>
1279 0	Irrigation	1	5/8	10057530	6/1/2016	32664	345 1 20'
							<b>345</b>
1279 0		1	3/4	13194070	6/1/2016	38023	1596 1 20'
							<b>1,596</b>
1280 0	Irrigation: front of	1	3/4	13077075	6/1/2016	3	0 1 20'
							<b>0</b>
1280 0	Residential: front	1	3/4	13077078	6/1/2016	3203	9 1 20'
							<b>9</b>
1282 0	Domestic	1	3/4	13077073	6/1/2016	10091	25 1 20'
							<b>25</b>
1282 0	Irrigation	1	5/8	98668424	6/1/2016	3	0 1 20'
							<b>0</b>
1286 0	Irrigation	0 SR	5/8	15600927	6/1/2016	0	0 1 20'
							<b>0</b>

6/6/2016

<u>Customer #</u>	<u>Location</u>	<u>Class</u>	<u>Units</u>	<u>Size</u>	<u>Serial No</u>		<u>Reading</u>	<u>Consumptn</u>	<u>Peric</u>
1286 0			0 SR	5/8	98624551	6/1/2016	5158	922	1 20'
								<b>922</b>	
								<b>5,720,724</b>	